

GROUP	MODEL
ELE	See Model List
NUMBER	DATE
163	May 2019
	-

## TECHNICAL SERVICE BULLETIN

PARASITIC DRAW INSPECTION AND REAR DOOR LATCH REPLACEMENT

This bulletin provides the procedure to inspect for a parasitic draw and, if necessary, replace one or both rear door latches on some of the following vehicles which may experience a discharged 12v battery. Follow the procedure in this bulletin to inspect the vehicle for a parasitic draw due to either of the rear door latches and, if necessary, replace the left and/or right rear door latch(es).

Model Year	Production Date Range	Model		
2018	September 26, 2017 through March 30, 2018	Niro Plug-in Hybrid (DE PHEV)		
2017-2018	August 25, 2016 through March 30, 2018	Optima Plug-in Hybrid (JF PHEV)		
2015-2018	July 15, 2014 through May 14, 2018	Soul EV (PSEV)		



File Under: <Electrical>

Circulate To: 

General Manager

Service Manager

Parts Manager

☑ Service Advisors ☑ Technicians ☑ Body Shop Manager ☑ Fleet Repair

SUBJECT:

## PARASITIC DRAW INSPECTION AND REAR DOOR LATCH REPLACEMENT

## **Inspection Procedure:**

- 1. Retain or record the customer's radio presets using a Memory Saver.
- Prepare the vehicle for a <u>parasitic draw</u> <u>inspection</u> by referring to steps 1 through 4 of the "Vehicle Parasitic Current Inspection" section of the "Maintenance → Power Train → Battery → Repair procedures" chapter in the applicable Shop Manual on KGIS.


#### NOTE:


- 1. Open the front doors and manually close the front door latches.
- 2. If the 12v battery is located under the hood, leave the hood open and if applicable, disconnect the hood switch.
- 3. If the 12v battery is located in the trunk, leave the trunk open and manually close the trunk latch.
- 3. After the vehicle is in sleep mode, observe the connected ammeter for a few minutes.
  - If the current does not go over 50mA, reinstall the negative (-) battery terminal in the reverse order of removal. No further action is required. Verify customer's radio presets were retained or restore, if necessary, using recorded information in step 1.
  - If the current goes over 50mA, proceed to the next step.
- 4. Disconnect the left rear door harness behind the rubber grommet, located at the B-pillar.

Allow the vehicle to go back to sleep mode and then observe the ammeter for a few minutes.

- If the current does not go over 50mA, replace the left rear door latch by following the door latch replacement procedure on page 3.
- If the current goes over 50mA, proceed to the next step.








SUBJECT:

## PARASITIC DRAW INSPECTION AND REAR DOOR LATCH REPLACEMENT

5. Disconnect the right rear door harness, located at the B-pillar.

Allow the vehicle to go back to sleep mode and then observe the ammeter for a few minutes.

- If the current does not go over 50mA, replace the right rear door latch by following the door latch replacement procedure on page 3.
- If the current goes over 50mA, further diagnosis or repair is required and not covered in this bulletin. File a separate claim if necessary.



### **Door Latch Replacement Procedure:**

 Replace the left and/or right rear door latch assembly (<u>per inspection result</u>) by referring to the "Body (Interior and Exterior) → Rear Door → Rear Door Latch → Repair procedures" chapter in the applicable Shop Manual on KGIS.

## \* NOTICE

On Optima Plug-in Hybrid (JF PHEV) vehicles, removal of the rear outside door handle is mentioned in the Shop Manual under repair procedures of the Rear Door Module; however, this is not necessary for replacement of the rear door

 Verify customer's radio presets were retained or restore, if necessary, using recorded information in step 1 of the Inspection Procedure.



Note: The rear door latch assembly may differ from model to model. Shown above is from a Niro Plugin Hybrid (DE PHEV).

SUBJECT:

# PARASITIC DRAW INSPECTION AND REAR DOOR LATCH REPLACEMENT

## AFFECTED VEHICLE RANGE:

Model	Production Date Range		
Niro Plug-in (DE PHEV)	September 26, 2017 through March 30, 2018		
Optima Plug-in (JF PHEV)	August 25, 2016 through March 30, 2018		
Soul EV (PSEV)	July 15, 2014 through May 14, 2018		

### REQUIRED PART:

Model	Part Name	Part Number	Figure
Niro Plug-in	LR Latch Assembly	81410 G5000FFF	
(DE PHEV)	RR Latch Assembly	81420 G5000FFF	
Opt. Plug-in	LR Latch Assembly	81410 D4000FFF	
(JF PHEV)	RR Latch Assembly	81420 D4000FFF	
Soul EV	LR Latch Assembly	81410 B2000FFF	
(PSEV)	RR Latch Assembly	81420 B2000FFF	Note: DE PHEV latch shown

### WARRANTY INFORMATION:

N Code: I14 C Code: ZZ4

Model	Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
DE PHEV, JF PHEV, PSEV	W	Refer to EPC	0	Parasitic Draw Inspection Only	81410F01	0.3 M/H	N/A	0
Ni a Di a la		W Refer to EPC	0	Parasitic Draw Inspection & Rear Door Latch Replacement (One Side)	81410F02	0.8 M/H	81410 G5000FFF	1 1
Niro Plug-in (DE PHEV)	\//						OR	
(DETTIEV)							81420 G5000FFF	
0 . 5					81410F02	1.0 M/H	81410 D4000FFF	
Opt. Plug-in (JF PHEV)							OR	
Soul EV (PSEV)							81420 D4000FFF	
					81410F02	1.2 M/H	81410 B2000FFF	
							OR	
(I OLV)							81420 B2000FFF	
Niro Plug-in		W Refer to EPC	0	Parasitic Draw Inspection & Rear Door Latch Replacement (Both Sides)	81410F03	1.2 M/H	81410 G5000FFF	1
(DE PHEV)	DE PHEV) pt. Plug-in						81420 G5000FFF	1
Opt. Plug-in					81410F03	1.5 M/H	81410 D4000FFF	1
(JF PHEV)							81420 D4000FFF	1
Soul EV						81410F03	1.9	81410 B2000FFF
(PSEV)	(V)	01410003	M/H	81420 B2000FFF	1			